

Energy and Minerals HSEC Initial Alert

Incident Number: 1000522550

Incident: Employee injures finger

Preliminary Classification: Medical Treatment Injury (MTI)

Critical Control: N/A

Operation / Project: Boron (RTB)

Location: Plant 5 Fusing

Date: 10/06/2019

Time: 13:00

Contact: Ernie Garcia Ernie.Garcia@riotinto.com

What happened:

A millwright was conducting maintenance on the pan conveyor at Plant 5. The task was to change some damaged rollers. While replacing the linkage the “tug-it” slipped. The momentum caused the millwright to impact a finger on the adjacent roller which caused an injury that required three stitches. Gloves were being worn.

Preliminary findings:

- Environment: High temperature
- Equipment: The piece of equipment failed when tension was being applied
- People: Millwright was wearing gloves, which may have reduced outcome

Initial learnings:

- Environment: N/A
- Equipment: Pending Investigation
- People: Pending Investigation



Roller where the finger was impacted